

## EXHIBIT E

### Reports Documenting Releases from SWMUs and AOCs at the Facility

1. Hart Crowser, August 1986, Removal of Underground Storage Tanks RE-01, RE-02 and RE-03, and Excavation of Contaminated Soil
2. Landau Associates, August 1986, Interim Report, Soil and Groundwater Contamination, Tanks RE-05 and RE-06
3. Landau Associates, May 1987, Report on Soil and Groundwater Contamination, Tanks RE-17 and RE-24
4. Hart Crowser, August 24, 1987, Preliminary Assessment of Soil and Groundwater Quality, Proposed Building 4-86
5. Landau Associates, Inc., February 9, 1989, Final Report, Soil and Groundwater Information;
6. ECOVA, October 13, 1989, UST Mitigation Final Report
7. Groundwater Technology, October 1989, Subsurface Environmental Assessment with Clean-Up Options, Vicinity Buildings 4-61, 4-79, 4-78 and 4-73
8. Landau Associates, November 1989, Report, Soil and Ground Water Conditions, Former Underground Tanks RE-17, RE-24 and RE-54
9. Groundwater technology, Inc., April 25, 1990, Subsurface Investigation for Sump SRE-2243 in Building 4-63 Compressor Room. (SWMU 179)
10. Hart Crowser, May 1990, Report for Subtitle I Underground Storage Tanks and Other Units
11. Science Applications International Corporation Technology Services Company, March 1991, RCRA Facility Assessment Final PR/VSI Report, Boeing Commercial Airplanes, Renton, Washington
12. Landau Associates, December 1991, Report, Soil and Groundwater Characterization Study, Underground Storage Tanks URE-05 and URE-06
13. CH2M Hill, December 1991, Building 4-78, Subsurface Soils Investigation
14. Groundwater Technology, April 1992, Report, Groundwater Remediation System Performance, Operation and Maintenance, August through September, 1991, Building 4-79
15. Landau Associates, April 1992, Report, Groundwater Sampling, November 1991, Underground Storage Tanks URE-05 and URE-06
16. Groundwater Technology, June 1, 1992, Groundwater Remediation System Performance, Operation and Maintenance, October through December 1991, Building 4-79
17. Groundwater Technology, June 29, 1992, Groundwater Remediation System Performance, Operation and Maintenance, January Through March 1992, Building 4-79
18. CH2M Hill, June 1992, URE-05, -06 Corrective Measure Study
19. Landau Associates, August 1992, Report, Groundwater Sampling, March 1992, Underground Storage Tanks URE-05 and URE-06
20. Landau Associates, August 1992, Groundwater Sampling, June 1992, Underground Storage Tanks URE-05 and URE-06

21. Burlington Environmental, May 1993, URE-38, URE-39, URE-40 Tank Closure and Soil Remediation
22. WESTON, June 1993, Corrective Measures, Performance Evaluation Report, Former Tanks URE-05 and URE-06
23. Burlington Environmental Inc., March 1994, Dangerous Waste Tank URE-036 Closure Report
24. SEACOR, March 17, 1994, Preliminary Soil and Groundwater Assessment Investigation, 4-42 Building Vapor Degreaser
25. Burlington Environmental, April 1994, Site Characterization Report, Former Renton Fuel Farm
26. SEACOR, April 27, 1994, Supplemental Soil and Groundwater Assessment Investigation, 4-42 Building Vapor Degreaser
27. SEACOR, April 27, 1994, Supplemental Subsurface Soil Assessment, 4-45 Building Sump Area
28. SEACOR, April 27, 1994, Supplemental Subsurface Soil Assessment Investigation at the 4-21 Building Sump and Storage Areas
29. SEACOR, August 15, 1994, Additional Soil and Groundwater Assessment Investigation, 4-42 Building
30. SEACOR, August 15, 1994, Off-Site Groundwater Assessment Investigation, 4-42 Building
31. Weston, September 1994, Feasibility report, In-Situ Bioremediation Assessment at Former Fuel Farm
32. Weston, February 2000, Building 4-65 Yard Sampling Report
33. Weston, June 2000, Building 4-20, Column G-6 Elevator Soil and Groundwater Sampling Report
34. Weston, September 2000, AOC-090 Interim Report, Building 4-65 Yard
35. Weston, August 2001, Building 4-20 Exterior, Column S-4 (AOC-092) Soil and Groundwater Sampling Report
36. Weston, August 10, 2001, Remedial Investigation Report, Boeing Renton Plant
37. URS, January 16, 2002, Draft Report, Building 4-79 Paint Booth Investigation Report, Boeing Renton Plant
38. URS, March 4, 2002, Draft Feasibility Study Work Plan Addendum
39. Geomatrix, June 23, 2004, Memorandum, Boeing Renton SWMU-179 Cleanup Results
40. Geomatrix, June 18, 2004, Memorandum, Additional Investigation of AOC-001, 002 and 003
41. Geomatrix, July 8, 2004, Memorandum, Boeing Renton AOC-090 Interim Action Results
42. Geomatrix, May 5, 2005, Memorandum, Boeing Renton AOC-050, 051 and 052 Soil Removal Action Results
43. Geomatrix, January 27, 2006, Memorandum, Boeing Renton AOC-001 and AOC-002 Interim Action Results
44. Geomatrix, January 22, 2007, Memorandum, Draft Additional Investigation of AOC-034 and -035, Building 4-41
45. AMEX Geomatrix, August 2008, Draft Pre-Cleanup Action Plan Investigation Results, Boeing Renton Facility